

APPROVED

JAN 13 1956

ARTEAIA OFFICE COPY

(SUBMIT IN TRIPLICATE)

U. S. Land Office **C**Lease or permit No. **048491 (G)**

Saunders

DISTRICT ENGINEER

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

RECEIVED
JAN 10 1956
U. S. GEOLOGICAL SURVEY
ROS WELL, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	X	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Saunders **2310** Dec. 189, 19 **55**
Well No. **9** is located **1330** ft. from **[N]** line and **330** ft. from **[E]** line of sec. **13**
S of **S** of **N** **17-S. 27-E. N.H.P.M.**
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Empire **Eddy** **New Mexico.**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 464' of 5½ - 14 # pipe set with 75 sacks cement.

Drilled plug - complete shut off.

RECEIVED
JAN 13 1956
U. S. GEOLOGICAL SURVEY
ARTEAIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **BEAN WHITE OIL COMPANY**Address **Box 638 Artesia, N.M.**

By

Title **Agent.**