

# NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

RECEIVED  
AUG 31 1942  
RECEIVED

## MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

Artesia, New Mexico

Aug. 3, 1942

Place

Date

OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the

E. Orcutt

F.E. Kepple

Well No. 1 in the

Company or Operator

Lease

NE SW SE

of Sec.

19

T.

17

R.

27

N. M. P. M.,

Red Lake

Field,

Eddy

County

The dates of this work were as follows: August 3, 1942

Notice of intention to do the work was ~~submitted~~ submitted on Form C-102 on July 23, 1942 and approval of the proposed plan was ~~obtained~~ obtained. (Cross out incorrect words.)

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

We filled hole with mud from 602 TD to 515' and set bridge and cement plug of 5 sax; then filled with mud to 75' and set bridge and cement plug of 5 sax; then filled with mud to surface and set regulation marker.

Witnessed by C. S. Powell Self Drilling Contractor  
Name Company Title

Subscribed and sworn to before me this 3 day of August, 1942

Charlie B. Glenn  
Notary Public

My Commission Expires March 3, 1945

My Commission expires

I hereby swear or affirm that the information given above is true and correct.

Name E. Orcutt

Position Owner

Representing E. Orcutt

Company or Operator

Address Box 144, Anton, Texas

Remarks:

Ray. Yarbrough  
Name  
OIL & GAS INSPECTOR  
Title

1. The first part of the report is a general description of the project and its objectives. This section should provide a clear and concise overview of the work that has been done and the results that have been achieved.

2. The second part of the report is a detailed description of the methods used in the study. This section should provide a clear and concise overview of the procedures that were followed and the data that were collected.

3. The third part of the report is a discussion of the results of the study. This section should provide a clear and concise overview of the findings and their implications for the field of study.

4. The fourth part of the report is a conclusion and a list of references. This section should provide a clear and concise overview of the main findings of the study and the sources of the information used in the report.

5. The fifth part of the report is a list of appendices. This section should provide a clear and concise overview of the additional information that is included in the report.

6. The sixth part of the report is a list of figures and tables. This section should provide a clear and concise overview of the visual information that is included in the report.

7. The seventh part of the report is a list of footnotes. This section should provide a clear and concise overview of the additional information that is included in the report.

8. The eighth part of the report is a list of references. This section should provide a clear and concise overview of the sources of the information used in the report.

9. The ninth part of the report is a list of appendices. This section should provide a clear and concise overview of the additional information that is included in the report.

10. The tenth part of the report is a list of figures and tables. This section should provide a clear and concise overview of the visual information that is included in the report.