



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_  
Lease No. **LC 069275-A**  
Unit \_\_\_\_\_  
**RECEIVED**

APR 13 1962

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 5, 1962  
Sparks Federal  
Well No. 1 is located 660 ft. from N line and 1980 ft. from E line of sec. 30  
C NE/4, NW/4 (1/4 Sec. and Sec. No.) 172 (Twp.) 27E (Range) New Mexico Prime (Meridian)  
Undesignated (Field) Eddy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3380 ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

A 15 sack plug was spotted across perforations 1260-1266.  
Spotted 665' of 4 1/2 casing.  
Spotted a 25 sack plug across the stub.  
Spotted a 10 sack plug on the surface with a marker.  
Mud was placed between all plugs.  
The pit was cleared and leveled.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Cabon Exploration Corporation

Address 211 N. Ervey Bldg., Room 1502

Dallas 1, Texas

By Tom Boyd, Jr.  
Title Production Manager

*Chlorophyll*