

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM OIL CONS. COMMISSION
Drawer DD
Artesia, NM 88210

Form Approved.
Budget Bureau No. 42-R1424

clsf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR

LATCH OPERATIONS

3. ADDRESS OF OPERATOR

Box 10108 LUBBOCK TX 79408

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1650 FNL & 990 FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

I. Tubing was run to 505'.

II. A cement plug was placed from 505' to 275' (35 SKS class H @ 4% CaCl)

III. The plug was tagged and the well was filled to surface @ 10 SKS class H @ 4% CaCl. Hall, Burton / Artesia, N.M. did the job.

IV. A permanent marker was set.

V. Location will be cleaned and put in to shape according to B.L.M. specifications.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Joseph B. Scheldt

TITLE

Agent

DATE

19 Aug 83

APPROVED BY

TITLE

DATE

7-2-86

CONDITIONS OF APPROVAL, IF ANY:

Post ID-2
9-23-83
P4A

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED
AUG 25 11 19 AM '83
BUREAU OF LAND MANAGEMENT
ROSENBLUTH