

(SUBMIT IN TRIPLICATE)

Land Office

Case No. 100-063623-8

Unit

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 23, 1960

Hanson

Well No. 7-A is located 2310 ft. from {N} line and 1650 ft. from {E} line of sec. 27

SW/4 NE/4 Sec. 27

(1/4 Sec. and Sec. No.)

16 South, 27 East

(Twp.)

(Range)

NMPM

(Meridian)

Undesignated

(Field)

Eddy

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3491 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mud logs, depths, and other important proposed work)

9-5/8" Hole New 7" Casing @ 150 feet circulated 50 sacks cement in place

We propose to drill out cement plugs with 6-1/4" bit and run

4-1/2" New Casing @ 1482 feet with 180 sacks cement, circulated and

attempt a completion in the Premier formation.

Drilling Contractor is Walker Drilling Company of Pecos, Texas.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Wayne J. Spears

Address 201 Three Cross

Roswell, New Mexico

By Samuel B. Spears

Title Agent