

(SUBMIT IN TRIPLICATE)

Land Office _____

Lease No. **LC-063623-2**

Unit **RECEIVED**

AUG - 9 1978

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS

**O. C. C.
ARTESIA, OFFICE**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 23, 1960, 19__

Hanson

Well No. **11-A** is located **1980** ft. from **21** line and **660** ft. from **E** line of sec. **27**

NE 1/4 SE 1/4 Sec. 27

(1/4 Sec. and Sec. No.)

16 South, 27 East

(Twp.)

(Range)

NMPM

(Meridian)

Undesignated

(Field)

Eddy

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

150 feet of 7 inch casing left in hole.

Well was plugged as follows:

1055-1005 with 10 sacks cement,

495-394 with 20 sacks cement,

230-157 with 15 sacks cement,

**Surface with 5 sacks cement, Heavy Mud between all plugs,
Marker on surface.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Wayne J. Spears**

Address **201 Three Cross**

Artesia, New Mexico

By **Wayne J. Spears**

Title **Operator**