

Land Office

Lease No.

Unit

RECEIVED

AUG - 9 1978

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUNDRY NOTICES AND REPORTS ON WELLS **O. C. C.**
ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 15

1961

#12 Hanson Roadwell A¹ ✓
Well No. _____ is located 2310 ft. from $\begin{Bmatrix} N \\ S \end{Bmatrix}$ line and 970 ft. from $\begin{Bmatrix} E \\ W \end{Bmatrix}$ line of sec. 27
NE1/4NW1/4 Sec. 27 T. 16 S., R. 27 E. M.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Dog Canyon Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3457 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tubing switched dry and filled with cement, squeezed open hole from total depth.

On outside of collars and pipe, filled up with cement.
Six 3 1/2" collars and 100 feet of tubing laid in hole.

Used 300 sacks cement for plugging.

RECEIVED

OCT 18 1961

GEOLOGICAL SURVEY

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Wayne J. Spears

Address 742 Petroleum Building

Roswell, New Mexico

By Mariott W. Hunt

Title Agent