

(SUBMIT IN TRIPLICATE)

Land Office **LC-062623-B**

Lease No. **RECEIVED**

Unit **AUG - 9 1978**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS** **O. C. C. ARTESIA, OFFICE**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<b>x</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**January 30**, 19 **61**

**Hanson A**

Well No. **13** is located **1650** ft. from **[N]** line and **2310** ft. from **[E]** line of sec. **27**

**SW/4 NE/4 Sec. 27 16 South, 27 East RMPM**

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

**Dog Canyon-Grayburg**

**Eddy**

**New Mexico**

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is **3506** ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**The above well was plugged as follows:**

**1000 - 950 feet with 10 sacks cement,  
450 - 350 feet with 20 sacks cement,  
180 - 105 feet with 15 sacks cement,  
Surface with 5 sacks cement, Marker on surface.**

**Total Depth 1460 feet**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

**Wayne J. Spears**

Company \_\_\_\_\_

Address **726 Petroleum Building**

**Roswell, New Mexico**

By **[Signature]**

Title **Agent**

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 062623-2  
Unit 9

RECEIVED

SEP 26 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 20, 1963

Well No. 13 is located 1650 ft. from {N} line and 2310 ft. from {E} line of sec. 27  
27 (1/4 Sec. and Sec. No.) 16 (Twp.) 27 (Range) N. (Meridian)  
Edgy (Field) Edgy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1000 20 foot cement plug (5 sacks) in top of surface pipe  
 set regulation marker  
 fill pit and clean and level location

RECEIVED  
SEP 24 1963  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company American Employers' Insurance Company

Address Box 437

Artesia, New Mexico

By E. C. Fultz

Title Agent