


U. S. LAND OFFICE Las Cruces
 SERIAL NUMBER 057674(a)
 LEASE OR PERMIT TO PROSPECT _____



LOCATE WELL CORRECTLY

UNITED STATES
 DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Daugherty

DEC 20 1976

O. C. C.
OFFICE

LOG OF OIL OR GAS WELL

Company Paul B. English Address _____
 Lessor or Tract Daugherty Field Red Lake State New Mexico
 Well No. 3-A Sec 3 T. 17S R. 27E Meridian N.M.P.M. County ddy
 Location 613 ft. N. of S. Line and 1000 ft. E. of W. Line of 990 3 Elevation 390
 (Check box if on section line)

The information given herewith is a complete and correct record of the well and all work done thereon so far as can be determined from all available records.

Signed _____

Date February 12, 1942

Title _____

The summary on this page is for the condition of the well at above date.

Commenced drilling March 25, 1942, 19____ Finished drilling March 30, 1942, 19____

OIL OR GAS SANDS OR ZONES

(Denote gas by G)

No. 1, from 615 to 650 (Gas) No. 4, from _____ to _____
 No. 2, from _____ to _____ No. 5, from _____ to _____
 No. 3, from _____ to _____ No. 6, from _____ to _____

IMPORTANT WATER SANDS

No. 1, from 264 to 270 No. 3, from _____ to _____
 No. 2, from _____ to _____ No. 4, from _____ to _____

CASING RECORD

Size casing	Weight per foot	Threads per inch	Make	Amount	Kind of shoe	Cut and pulled from	Perforated		Purpose
							From—	To—	

MUDDING AND CEMENTING RECORD

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used
	<u>180 ft.</u>			<u>set</u>	<u>?</u>

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ Depth set _____
 Adapters—Material _____ Size _____

SHOOTING RECORD