

Form 9-311a
(May 1939)

(SUBMIT IN TRIPLICATE)

U. S. Land Office **Las Cruces**

Lease or permit No. **087674-A**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 14, 19 **45**

Well No. **2** is located **2210** ft. from **N** line and **2210** ft. from **E** line of sec. **8**
SW/4 **8** **17** **27** **MM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Red Lake **May** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Shot from 1,875 to 1,860

With 50 quarts in 4" shell

No increase in gas

J. A. English

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **P. B. English**

Address **Box 323**

Artesia, New Mexico.

By

PB English
Owner.

Title