

APPROVED
FEB 10 1964

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **LC-057674(a)**
Unit **H**

copy to SD

RONNIE F. SHOOK
ACTING DISTRICT ENGINEER

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 6, 19 **64**

Daugherty ✓

Well No. **4** is located **1051** ft. from **EX** line and **1672** ft. from **EX** line of sec. **3**

SE/4 SW/4 Sec. 3

(1/4 Sec. and Sec. No.)

17N

(Twp.)

27E

(Range)

MTN

(Meridian)

Daugherty (San Andres)

(Field)

Bddy

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **3494** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set cement from TD 2061' to 1030'. Loaded hole w/aquegel mud from 1030' to 20'. Set cement from 20' to surface. Set marker. Cleaned location. Plugged and abandoned.

*Comm. Prod.
3221 bbls.*

RECEIVED
FEB 11 1964
D. C. C.
ARTERIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **DELMY-TAYLOR OIL CORPORATION**

Address **P. O. Box 1821**

Midland, Texas

By

Title

District Clerk

SECRET