

Land Office Las Cruces  
Lease No. 050158  
Unit P

MAR 18 1958 (SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 15, 1958

Well No. 4X - Harburt is located 380 ft. from XX line and 990 ft. from E line of sec. 26  
SE 38 Sec. 26 17 S 27 E 104PM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Empire Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

January 15, 1958:

Cement plug at bottom, approximately 424 feet, with 10 sacks cement. Mud from bottom to top of pipe. Knocked off 6-5/8" pipe at 250 feet and pulled, and placed cement plug. Mud to surface with regulation marker of 4" pipe.

Plugging done by C. O. Fulton, Artesia, New Mexico.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company PAT EVANS  
Address P/ O. Box 333  
Artesia, New Mexico  
By Juanita Denton  
Title Juanita Denton, Agent