

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN T
(Other instruc
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-064050-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	RECEIVED	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION	JAN 3 1968	8. FARM OR LEASE NAME TRIGG Federal
3. ADDRESS OF OPERATOR BOX 68, HOBBS, N. M. 8824	NAME CHANGED: FROM: PAN AMERICAN PETROLEUM CORPORATION TO: AMOCO PRODUCTION CO. EFFECTIVE: 2-1-71	9. WELL NO. 1
4. LOCATION OF WELL (Report location, depth, and direction of hole by survey. See also space 17 below.) At surface	330' FSL x 330' FEL Sec. 34 (UNIT P, SE 1/4 SE 1/4)	10. FIELD AND POOL, OR WILDCAT EMPIRE Obo
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3625' R.D.B.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 34-17-27 NMPM
		12. COUNTY OR PARISH EDDY
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☒	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

In an effort to increase productivity, Fracture zone 5592-5608' w/ 40,000 gal gelled brine + 1" Sand per. gal. Evaluated.

Prior - pmp. 42 BO + 0 BW 24 hours.

After - pmp. 129 BO + 8 BW 24 hours. GOR 535.

TD- 5638

OC- 12-7-67
Comp- 12-26-67

PBD- 5611

PERFS : 5592-5603'.

4 1/2" CSA 5638' Int. line.

RECEIVED
JAN-2-1968
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

014- USGS- BUREAU

1- NSM

1- SUSP

1- RRY

APPROVED
JAN - 3 - 1968
R. L. BLUMHART
DISTRICT ENGINEER

*See Instructions on Reverse Side