

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor
Joanna Prukop
Cabinet Secretary

Lori Wrotenbery

Orector

Oil Conservation Division

1/15/2003

Rojo Grande Co. LLC PO Box 248 Artesia, NM 88210

Dear Operator:

The following inspection(s) indicate one or more violations as described in the detail section below. The inspection(s) indicate the well, equipment, location or operational status failed to meet standards of the New Mexico Oil Conservation Division. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken **immediately** and the well(s) brought into compliance. The detail section below indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division.

Please notify the proper district office of the Division, in writing, of the date corrective actions are completed so that arrangements can be made to reinspect the well and /or facility.

## Inspection Detail Section

API No	Well Name	No	UL	Sec	Тwр	Rng	Violation
30-015- 00674	Ramapo	2	K	36	17	27	Violation Rule 701 – Unauthorized injection – Water tank plumbed into casing at the wellhead. This must be disconnected <b>immediately.</b>

In the event that a satisfactory response is not received to this letter of direction on or before January 21, 2003, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well(s). Such a hearing may result in imposition of Civil Penalties for your violation of OCD Rules.

Sincerely,

Oil Conservation Division, District II

Vou