		<i>*</i> -							EIVED		
			EXICO OIL					ION	FORM C-103		
			ELLANE					.5). C. C.		
Name of Company	· · · · · · · · · · · · · · · · · · ·	(Submit to ap		trict O			mission R	ule 1106) L	ESIA, OFFICE		
Lease	Kersey	& Company		·······	Addres	Bo		Artesia, Ne	w Mexico		
	Ramapo		Well No.	Un	it Letter I	Section 36	Township	17 5	Range 27E		
Date Work Performed		Pool E	mpire Abo				County	Eddy			
Beginning Drillin	0		IS IS A REPO				te block)				
Plugging	g Operatio	ons [A]	Casing Test		ement Job	[] Other (Explain):			
Detailed account of wo	rk done		•		· · · · · · · · · · · · · · · · · · ·						
The cement of 4000 # and sh	ircula	ated to sur 7 was found ersey	face, afte complete Position BELOW FOR	n let REME	artner DIAL WO	et 48 C DRK RE	hrs. th	e well was	with 2% Gel. pressured to & Company		
F Elev. T D			PBTD		ATA	Producing Interval		Completion Date			
Tubing Diameter	Ding Diameter			Oil String Diam		Diamat					
		Tubing Depth				S DIRMEL	er	Oil String	; Depth		
Perforated Interval(s)											
Open Hole Interval					Producing Formation(s)						
			RESU	LTS O	FWORK	OVER					
Test Date Test Te		Oil Product BPD		Gas Production MCFPD		Water Production BPD		GOR Cubic feet/Bl	Gas Well Potential MCFPD		
Before Workover							· · · · · · · · · · · · · · · · · · ·				
After Workover				*							
	NSERVA				I hereb to the l	y certify best of m	that the in y knowledg	formation given ;e.	above is true and complete		
Approved by MLC	Iru	F	······································		Name	17					
Title	<u> </u>	Myon	7		Mame	Na	1 ARD	Cene.			
	in an tak	strong	2		Position		wner	Kersen)		

lo. Copies Reacived	<u> </u>						
DISTRIBUTION							
	ļ	NO. SOLUTIONED					
Minghas A		/					
AT 18 4		i	1				
AREA STAR			1				
TARE LAKE CONTAIL			1				
1. S. s. S.							
TOANS TO ALL SE		·	1				
4116 ₁		/	1	~			
UPERU CHIMBE		s = −meren i se s s s s santa	6				

ж. .

.