

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lead Office Las Alamos
Lease No. 60012
Unit Lease

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 11, 1944

Well No. 4 is located _____ ft. from N line and _____ ft. from E line of sec. _____

60012 (Lease No.) 172 (Twp.) 27E (Range) 10N (Sec.)
Alamosa (Field) Eddy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate measuring jobs, cementing points, and all other important proposed work)

Well abandoned and plugged account no water encountered.
February 1952.

This report misfiled December 1942 without proper approval.
Following information being added as of Feb. 26, 1952.

Well was completed at total depth of 472' during Feb. 1942 and produced only a short time. Was plugged and abandoned during November 1942. The casing was cemented at 420' with 60 sacks. Dumped 15 sacks cement on bottom and filled to surface with mud and cemented marker.

GEOLOGICAL SURVEY

RECEIVED

FEB 11 1944

I understand that this report of work must be approved by the District Engineer, New Mexico.

Company _____

Address _____

By Rudolph Johnston
Title _____