

(SUBMIT IN TRIPLICATE)

Land Office **ARTERIA**

Lease No. _____

Unit **RECEIVED**

APPROVED
MAY 28 1962
A. R. BRUNN
ACTING DISTRICT ENGINEER

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 17th, 1960

Number

Well No. **1** is located **1300** ft. from **130** line and **330** ft. from **E** line of sec. **8**
16 South, **28** East
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated **Eddy** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The above captioned well was plugged as follows:

- 1305-1255 feet with 10 sacks cement,
 - 745-644 feet with 20 sacks cement,
 - 480-407 feet with 15 sacks cement,
 - surface with 5 sacks cement,
 - heavy mud between all plugs with marker at surface.
- Total depth 1824 feet.

RECEIVED

OCT 20 1960
U. S. GEOLOGICAL SURVEY
ARTERIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Wynne J. Spurns

Company _____

201 Three Cross Drive

Address _____

Roswell, New Mexico

By **Wynne J. Spurns**
Agent

Title _____