

RECEIVED

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

FEB 7 11 25 AM '91

SUNDRY NOTICES AND REPORTS ON WELLS

CARL
AREA

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR
Kersey & Company

3. ADDRESS OF OPERATOR
P.O. Box 316, Artesia, NM 88211-0316

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990/S 990/E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON* plug

(other)

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well completed with:

499' 8 5/8" casing with 50 Sacks cement
1577' 2 7/8" casing with 360 Sacks with 4 1/2 Gall
Perforated 1505/25' 1554/64'
Plan to plug well by filling 2 7/8" casing back
to surface with cement grout and install marker.

Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED David Kersey TITLE Co-Owner

DATE Feb. 5, 1991

APPROVED BY David P. Hays TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

DATE 3-17-92