

ARTESIA OFFICE COPY
(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 020053A

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Unit
GEOLOGICAL SURVEY

RECEIVED

APR 5 1944

SUNDRY NOTICES AND REPORTS ON WELLS

Artesia, New Mexico

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 4, 1944

Well No. 74 is located 2310 ft. from S line and 330 ft. from E line of sec. 10

34 13N 17E 20N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
100 4-10 Doña New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 2222 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to run 2" open end tubing to the bottom of the well through a Hercules stripper head, fill the well with oil, then have Halliburton pump cement into the well plugging back from 1,700' to 1,500', then pull the tubing out to 1,500' and wash out with oil. Let set for approximately seven days before going back into well.

Noted
J. C. Vandeventer

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southern Union Gas Company

Address 110 South Canal Street

Carlsbad, New Mexico

By H. O. Oldham

Title District Manager