

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**

Lease No. **045818 (a)**

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Nov. 27 1945

19. 45

Well No. **222** is located **130** ft. from **S** line and **44** ft. from **W** line of sec. **12**

SW

(1/4 Sec. and 1/4 Sec. No.)

173

122

(Range)

122

(Section)

Empire

(Field)

El Paso

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We are having trouble with water coming into the hole at the above well, at or about 130'; so as stated in the application for permit to drill we desire to set casing (8") and seek to stay the red bed saving trouble, this casing, as is stated in the application, will be pulled when the 7" production string is run and cemented.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company **A.H. Hoyer an Independent producer**

Address _____

By _____

Title _____