

(SUBMIT IN TRIPLICATE)

U. S. Land Office **145 (RECEIVED)**
Lease or permit No. **015818 (A)**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 8, 19**51**

Well No. **9** is located **2310** ft. from **IN** line and **990** ft. from **E** line of sec.
16 (1/4 Sec. and Sec. No.) **17E** (Twp.) **28E** (Range) **N 1/2 P 1/2** (Meridian)
Empire (Field) **ddy** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled from 526' to 510'. Well was put back on pump May 24 with no increase in production.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **A. H. BAYER**
 Address **Box 638**
Artesia, New Mex.

By **W. W. Byers**
 Title **Agent**