

ARTESIA OFFICE COPY

(SUBMIT IN TRIPLICATE)


UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Project Number G-2044
Approved October 12-6-24

Lead Office _____

Lease No. 12-00000-9 (a)

State _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANT		SUBSEQUENT REPORT OF SHUTTING OR ABANDONING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHUT OR ABANDON		SUBSEQUENT REPORT OF REABANDONMENT	
NOTICE OF INTENTION TO PUMP OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(RECORDS ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 8, 1929

Well No. 1 is located 2320 ft. from N line and 330 ft. from E line of sec. 19

17 (Twp.) 28 (Range) WEST (Section)
Edgely (County or Subdivision)

RECEIVED
DEC 10 1929
U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

When commencing reported depths to obtaining casing shoe logs, weights, tool lengths of proposed casings, indicate casing joint, cement, and all other important proposed work.

This well was drilled to a total depth of 3320 feet. Did not show for any production below premier pay at a depth of 1975 feet to 1978 feet. We set a permanent Halliburton bridge plug at 2000 feet, cemented on top of it to 2075. We treated premier pay with 20,000 pounds of sand and 200 gallons of water. Production before treating was 2 barrels a day. After treating 2 barrels a day.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Rayburn Oil Company

Address Box 65

Edgely, New Mexico

E. J. [Signature]
Title Owner