

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. LC 065729
Unit 6689

RECEIVED

MAR 3 1960

SUNDRY NOTICES AND REPORTS ON WELLS

C. C. C.

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	ARTESIA, OFFICE
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Change to injection well	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Red Lake Premier Sand Unit Sec. 12
Injection well
Well No. 1 is located 2310 ft. from [N] line and 1650 ft. from [E] line of sec. 20
34 1/4 NE 1/4 Section 20 17 28 R11E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Red Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well drilled August 8, 1939
Converted into injection well April, 1957
8 1/4" casing at 476' cemented with 20 sacks cement
Water going into zones at 1904 - 1926.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Red Lake Premier Sand Unit - Kersey & Company
Address Box 305, Artesia, New Mexico

By Harold Kersey
Title Owner