

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office ~~Las Cruces~~

Lease No. LC 048479 (C)

Unit 1600

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<div style="text-align: right;">O.C. # _____</div> <div style="text-align: right;">ARTESIAN OFFICIAL _____</div>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Change to injection well	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Red Lake Cr. Sec. 20
Well No. 2 is located 990 ft. from [N] line and 1650 ft. from [E] line of sec. 20
Section 20
17 (Twp.) 28 (Range) 10N (Meridian)
Red Lake (Field)
Eddy (County or Subdivision)
New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

*well drilled 1944
Converted to Injection well March, 1958
8 1/4" casing at 477' cemented with 50 sacks
7" casing at 1820' cemented with 100 sacks
*water going into zone at 1920-1955'

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Red Lake Premier Sand Unit - Kiersey & Company

Address Box 305, Artesia, New Mexico

By Natasha Kirsan
Title Owner