


SWD No. 237

+2-

- (5) That the operator shall immediately notify the Supervisor of the Division's Artesia District Office of the failure of the tubing, casing, or packer in said well or the leakage of water from or around said well and shall take such steps as may be timely or necessary to correct such failure or leakage.

Sincerely,

A handwritten signature in dark ink, appearing to read "Joe D. Ramey", is written over the typed name and title.

JOE D. RAMEY

Division Director

JDR/OS/og

cc: Oil Conservation Division  
Drawer DD  
Artesia, New Mexico