

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION RECEIVED BY  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501  
JAN 30 1984

O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Marbob Energy Corporation	8. Farm or Lease Name NG Phillips St.
3. Address of Operator P.O. Drawer 217, Artesia, N.M. 88210	9. Well No. 3
4. Location of Well UNIT LETTER <u>P</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>17S</u> RANGE <u>28E</u> NMPM.	10. Field and Pool, or Wildcat Artesia Qn Grbg SA
11. Elevation (Show whether DF, RT, GR, etc.) 3666' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/12/84 This well was plugged and abandoned as follows: Set 25 sack plug @ 2100', tagged @ 1875'; cut casing @ 1050', could not pull loose, shot casing again @ 1050', still would not pull loose, squeezed casing @ 1050' w/150 sax, came out of hole, perforated 600', squeezed 150 sax, came out of hole, shut down. Will install dry hole marker after drilling NG Phillips State #36.

Post ID-2  
2-3-84  
P.H.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Carolyn Quis</u>	TITLE <u>Production Clerk</u>	DATE <u>1/26/84</u>
APPROVED BY <u>Larry Brooks</u>	TITLE <u>Geologist</u>	DATE <u>3-9-84</u>
CONDITIONS OF APPROVAL, IF ANY:		