Form C-105

~

L CONSERVATION COMMENSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

day of, 1		Position Representing			
day of, 1	19				
day of, 1	19				
Subscribed and sworn before me this, 19, 19,		I hereby swear or affirm that the information given above is true and correct. Name			
The dates of this work were as follows: Notice of intention to do the work was (was not) s and approval of the proposed plan was (was not) of DETAILED ACCOUNT OF Ran 1668' of 7" casing come mud circulated to the surfa 20, 1945. Result: Complete water sh Witnessed by <u>E. F. Mc Crory</u> Name	btained. WORI ented ace.	d on Form C-102 on (Cross out incorrect X DONE AND RESU with 50 sacks of Let set 72 hour	words.) JLTS OBTAIN cement pred rs, drilled	ED eeded by i plug May	
Red Lake Field,		, T, N. M. T. M. Eddy May 20, 1945			
NW NW NW of Sec.	26	, T. <u>17</u>	, R. Eddy	<u>20</u> , N	. M. P. M.,
Red Lake Oil Company Company or Operator		Lease			
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO. Gentlemen: Following is a report on the work done and the resu	l ts obta	ined under the headi	ng noted abov	e at the	
ANT CONTRACTOR OF CONTRACTOR		Place		Date	
,	Art	esia, New Mexic	10 J	une 1, 1949	5
REPORT ON RESULT OF PLUGGING OF WELL					
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	Χ	REPORT ON DEEPENING WELL		-	
ICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING			
REPORT ON RESULT OF SHOOTING OR CHEM-		REPORT ON REPAIRING WELL			

١