

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

REC FORM C-193
E.O. 13551

MAR 29 1961

Name of Company Kersey & Company Red Lake Premier Sand Unit				Address Box 316, Artesia, New Mexico			
Lease Tigner	Well No. 1	Unit Letter L	Section 28	Township 17S	Range 28E		
Date Work Performed Feb.-Mar. 1961	Pool Red Lake			County Eddy			

THIS IS A REPORT OF: (Check appropriate block)

Beginning Drilling Operations
 Casing Test and Cement Job
 Other (Explain): **Set liner**
 Plugging
 Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Used 345.05' of 4 1/2" 9.5# liner - bottom of liner at 2007'. Top of liner at 1662'. Used 140 sacks of cement. While perforating after cement, found that we had failure on cement job, cement had channelled. Set RTTS tool of Halliburton in top of liner and pumped in 50 sacks more of cement, leaving cement in liner and 50' above liner after reversing out when packer released and tubing raised 50'. Drilled out cement to T.D. and found cement job O.K.

Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval			Producing Formation(s)	

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by <i>M L Armstrong</i>	Name <i>Harold Kersey</i>		
Title OIL AND GAS INSPECTOR	Position Owner		
Date MAR 29 1961	Company Kersey & Company		

**OIL CONSERVATION COMMISSION
ARTESIA DISTRICT OFFICE**

No. Copies Received 4

DISTRIBUTION

	NO FORWARDED	
OPERATOR	2	
SANTA FE		
PRODUCTION OFFICE		
STATE LAND OFFICE		
U. S. G. S.		
TRANSPORTER		
FILE		✓
BUREAU OF MINES		