

NUMBER OF COPIES RECEIVED <b>4</b>	
DISTRIBUTION	
SANTA FE	
FILE	<b>1-</b>
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	<b>12</b>

# NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company <b>Bedingfield</b>				Address <b>Drawer M Artesia, New Mexico</b>			
Lease <b>Aston &amp; Fair 1 X</b>		Well No <b>1 X</b>	Unit Letter <b>D</b>	Section <b>31</b>	Township <b>17</b>	Range <b>28-E.</b>	
Date Work Performed		Pool <b>Red Lake</b>		County <b>Eddy</b>			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain):
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Well has not been producing, but plans are being formulated for a waterflood in this area, and the well will be put back on production as soon as waterflood is completed

RECEIVED  
SEP 3 1964  
D. C. C.  
ARTESIA. OFFICE

Witnessed by	Position	Company
--------------	----------	---------

### FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

#### ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	

Perforated Interval(s)

Open Hole Interval

Producing Formation(s)

#### RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

#### OIL CONSERVATION COMMISSION

Approved by

Title

Date

SEP 2 1964

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

Position

Company

Owner & Operator.

J. F. Bedingfield