

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

JAN 28 1972

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. 647 |
| 7. Unit Agreement Name |
| 8. Farm or Lease Name M. Yates |
| 9. Well No. 2 |
| 10. Field and Pool, or Wildcat Artesia |
| 12. County Eddy |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

| |
|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A |
| 2. Name of Operator Atlantic Richfield Company |
| 3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201 |
| 4. Location of Well UNIT LETTER O , 250 FEET FROM THE South LINE AND 2390 FEET FROM THE East LINE, SECTION 33 TOWNSHIP 17-S RANGE 28-E NMPM. |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3660' GR |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|--|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged and abandoned in the following manner:
Displaced 30 sx Class H cement in 8-5/8" casing to 635'.
Shot off 8-5/8" casing @ 370'. Pld 8-5/8" casing. Spotted
30 sx cement half in & half out of 8-5/8" stub. Spotted
25 sx cement across 10" shoe @ 298'. Set 10 sk cement plug in
surface. Erected dry hole marker. Well P & A 1/25/72. 9#/gal
gel mud was left between all plugs. 10" casing remains intact.

Your office will be notified when location is ready for inspection.

est. left hole - 8 5/8" from 370' to 298'
10" 0 - 298'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *W. D. Litcher* TITLE Dist. Drlg. Supervisor DATE 1/26/72

APPROVED BY *John M. ...* TITLE OIL AND GAS INSPECTOR DATE MAR 13 1973

CONDITIONS OF APPROVAL, IF ANY: