

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Reisler & Yates et al 302 Carper Building, Artesia, New Mexico
(Address)

LEASE State 647 Tr. 7 WELL NO. 133 UNIT J S 24 T 17S R 28E

DATE WORK PERFORMED 10-15-56 to 11-1-56 POOL Artesia

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Drilled 10" hole to 385'. Cemented w/ 75 sacks. Found water at 410'. Drilled to 468' and set 7" s/ 35 sacks. More water upon drilling shoe. Recemented w/ 50 sacks. Still had water coming from 468-85'. Knocked off 7" at 120' and 8 5/8" at 100', and pulled from hole. Filled hole with dirt. Skidded five feet and drilled new hole to 540'. Ran 8 5/8" to 540' and cemented w/ 75 sacks. Upon drilling plug, hole was dry. Resumed drilling.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name M L Armstrong

Name Vilas H. Nelson

Title OIL AND GAS INSPECTOR

Position _____

Date 10-15-56

Company Reisler & Yates et al

OIL CONSERVATION AND PROTECTION	
ACTION	
No. 1000	4
2	