

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

ARTESIA DISTRICT

COMPANY Resler & Yates et al 302 Carper Building, Artesia, New Mexico
(Address)

LEASE State 647 - Tract 7 WELL NO. 135 UNIT L S 35 T 17S R 28E
DATE WORK PERFORMED 12-13 to 12-15-56 POOL Artesia

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

**Drilled 8 3/4" hole to 622'. Ran 611' of 7" surface casing and cemented w/75 sacks.
After 24 hours, drilled plug and started drilling w/ air. Hole was dry.**

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:
DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		
	(Company)	

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name M. J. Armstrong
Title Supervisor
Date Dec 28, 1956

Name Vilas S. Sherson
Position _____
Company Resler & Yates et al

OIL COMPANY	
ADDRESS	
No. 1	4
2	
12	