

**APPROVE**

APR 12 1963

RONNIE E. SHOOK  
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_

Lease No. **MM 0579-A**

Unit \_\_\_\_\_

RECEIVED

APR 15 1963

## SUNDRY NOTICES AND REPORTS ON WELLS

ARTESIA, OFFICE

|  |  |          |
|--|--|----------|
| NOTICE OF INTENTION TO DRILL                   | SUBSEQUENT REPORT OF WATER SHUT-OFF        |          |
| NOTICE OF INTENTION TO CHANGE PLANS            | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |          |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF     | SUBSEQUENT REPORT OF ALTERING CASING       |          |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |          |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE        | SUBSEQUENT REPORT OF ABANDONMENT           | <b>X</b> |
| NOTICE OF INTENTION TO PULL OR ALTER CASING    | SUPPLEMENTARY WELL HISTORY                 |          |
| NOTICE OF INTENTION TO ABANDON WELL            |  |          |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Lease No. **I**

April 9, 1963, 1963

Well No. **I** is located **2310** ft. from **N** line and **770** ft. from **E** line of sec. **4**Lot **5**, Section **4** (1/4 Sec. and Sec. No.) **16-S** (Twp.) **29-E** (Range) **100M** (Meridian)**Wildcat** (Field) **Edley** (County or Subdivision) **New Mexico** (State or Territory)The elevation of the derrick floor above sea level is **3713** ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On March 6, 1963, the above captioned well was plugged and abandoned in the following manner by Denton Oil Well Cementing Company: Loaded hole with mud prior to placing cement plugs, utilizing tubing. Cement plugs were placed from T.D. to 3050', 1580-1480, 750 - 650', 350-250 and 21' to surface. A marker was installed and the location cleaned. All pipe was pulled from the hole.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Jack L. McClellan**Address **Box 348****Roswell, New Mexico**By **Jack L. McClellan**  
Title **Operator**