E IEACE

Form 9-331 Dec 1973

1. oil

well

below.)

AT SURFACE:

AT TOTAL DEPTH:

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR P.O. Box 128

AT TOP PROD. INTERVAL:

REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

gas

well

General American Oil Company of Texas

Drawer DD Artesia, NN 88210

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,

other Water Injection

Loco Hills, New Mexico 88255

660' FSL and 1980' FEL

SUBSEQUENT REPORT OF:

LC-061638
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME RECEIVE
8. FARM OR LEASE NAME Brewer MAR 1 0 198
9. WELL NO. #19 O. C. D.
10. FIELD OR WILDCAT NAME ARTESIA, OFFICE High Lonesome
11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Sec. 12, T-16S, R-29E
12. COUNTY OR PARISH 13. STATE Eddy New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD 3738 DF

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned as follows:

- 100' Plug was set from 2106'-2006' to cover open hole section 2106'-2077'.
- Perforated 4 holes @ 1090', top of Yates, and squeezed 55 sacks of cement into formation.
- 3. Perforated 4 holes @ 475', 25' above top of salt, and squeezed 55 sacks of cement into formation.
- Perforated 4 holes @ 350', water zone, and squeezed 55 sacks into formation.
- 10 sack plug-was set at surface.
- Permanent well marker was erected.
- Location, road was cleaned, ripped and re-seeded.

AUG 2 7 1982

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct Field SIGNED Jandell M. Llauking title Superintendent DATE				OH & GAS MINERALS MGMT. SERVICE ROSWELL, NEW MEXICO August 26, 1982		Ft.
APPROVED BY	APPROVED (THE APPROVAL, IF ANY:	is space for Federal or State office use) TITLE	_ DATE		~ N	Th

9 1983

JAMES A. GILLHAM DISTRICT SUPERVISOR

ee Instructions on Reverse Side