


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Los Cruces  
Lease No. 6163  
Unit 1



RECEIVED  
ACTING DISTRICT ENGINEER

SUNDRY NOTICES AND REPORTS ON WELLS

|  |  |  |                                     |
|--|--|--|-------------------------------------|
| NOTICE OF INTENTION TO DRILL                   |  | SUBSEQUENT REPORT OF WATER SHUT-OFF        | <input checked="" type="checkbox"/> |
| NOTICE OF INTENTION TO CHANGE PLANS            |  | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |                                     |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF     |  | SUBSEQUENT REPORT OF ALTERING CASING       |                                     |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL |  | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |                                     |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE        |  | SUBSEQUENT REPORT OF ABANDONMENT           |                                     |
| NOTICE OF INTENTION TO PULL OR ALTER CASING    |  | SUPPLEMENTARY WELL HISTORY                 |                                     |
| NOTICE OF INTENTION TO ABANDON WELL            |  |  |                                     |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Loco Hills, N. M. February 10, 1959

Well No. 5 is located 1980 ft. from [N] line and 1980 ft. from [E] line of sec. 14

SW 1/4 NE 1/4 SEC. 14 16-6 29-1 N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
HIGH LOBOS Edgy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3729 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On February 2, 1959, we ran 249' of 7" OD Std 23# used JS casing to 2532' and cemented with 150 sacks cement.

After allowing to stand cemented for 72 hours we pressured up on casing to 2800 psig. Held pressure OK. We then drilled plug, bailed hole down and re-ran bailer. As shut-off tested OK, drilling was resumed.

Cementing and pressure testing was done by Denton Oil Well Cementing Company.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company GENERAL AMERICAN OIL COMPANY OF TEXAS

Address P. O. BOX 416

LOCO HILLS, N. M.

By [Signature]  
R. J. Beard

Title District Superintendent