

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

RECEIVED
AUG 23 1954
103
(Revised 7/1/52)

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	X	REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

Aug. 17, 1954

Bunice, N.Mex.

(Date)

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

J.C.Clower

Atkins State

(Company or Operator)

(Lease)

J.C.Clower

(Contractor)

Well No. 2 in the S W 1/4 S W 1/4 of Sec. 16

T. 16 S R. 29 E High Lanesome Pool, Eddy County.

Aug. 15, 16, 1954

The Dates of this work were as follows:

Notice of intention to do the work (~~was~~) (~~was not~~) submitted on Form C-102 on Verbal permission Aug. 14 54
(Cross out incorrect words)
and approval of the proposed plan (was) (~~was not~~) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Well started July 30, 1954 T.D. Aug. 14, 54. Drilled to 1869 dry.
8 5/8 pipe set at 476 ft. 7 O.D. pipe set at 1616 ft. through the red sand water which was drilled from 1862 ft. to 1600 ft. filled
15 sacks cement was used for bottom plug, hole was then to bottom of 7 O.D. with mud. 7 O.D. pipe was then pulled. Wood plug was set in reduced hole at 1616 ft. 10 sacks cement was dumped on this plug. Wood plug was set at 1575 ft. 12 sacks cement was dumped on this plug.
8 5/8 pipe was then pulled. Wood plug was set at 475 ft. 5 sacks cement was dumped on this plug, hole was filled with mud, 6 inch pipe was cemented in top for marker.
This well was drilled with cable tools.

Witnessed by

M. E. Hancock

(Name)

J.C.Clower

(Company)

Driller

(Title)

Approved:

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

Position

Representing

Address

Box 380 Bunice, N.Mex.

(Title)

(Date)

No. Code Date
100-100000-100000

— *Journal of the American Medical Association*, 1967, 202: 1025-1026.

...and the

THE UNIVERSITY OF CHICAGO

—