

Land Office New Mexico  
 Lease No. NM-0916  
 Unit Simmons Federal

(SUBMIT IN TRIPLICATE)

UNITED STATES  
 DEPARTMENT OF THE INTERIOR  
 GEOLOGICAL SURVEY

RECEIVED

SEP 19 1963

SUNDRY NOTICES AND REPORTS ON WELLS

O. C. C.

ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	X
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 6, 19 62

Well No. 2 is located 330 ft. from [X] S line and 330 ft. from [E] W line of sec. 26

SE/4 26 16-S 29-E NMPM  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Forest Eddy New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3687 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Moved in and rigged up Expert Well Service Unit. Installed BOP. Ran 2" tbg. to 2665'. Halliburton spotted 50 sx cement 2265-2665'. Pulled tbg. Dialog ran free point indicator and indicated 5 1/2" csg. stuck @ 1779'. Cut 5 1/2" csg. @ 1771'. Pulled 1771' of 5 1/2" csg. Ran 2" tbg. to 1825'. Halliburton spotted 50 sx Portland Neat cement 1725-1825'. Spotted 50 sx cement 1015-1115, 50 sx cement 420-520' and 50 sx cement surface to 30'. Dumped 25 sx cement around outside of 10 3/4" csg. @ surface. Installed regulation monument. Mud laden fluid between plugs. Plugged & abandoned 5/26/62.

RECEIVED

JUN 8 1962

U. S. GEOLOGICAL SURVEY  
 ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Socony Mobil Oil Company, Inc.

Address Box 2406

Hobbs, New Mexico

By

Title Senior Clerk