

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las CrucesLease No. 064832Unit Levers

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|---|---|----|
| NOTICE OF INTENTION TO DRILL..... | SUBSEQUENT REPORT OF WATER SHUT-OFF..... | 25 |
| NOTICE OF INTENTION TO CHANGE PLANS..... | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... | 26 |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... | SUBSEQUENT REPORT OF ALTERING CASING..... | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF REDRILLING OR REPAIR..... | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... | SUBSEQUENT REPORT OF ABANDONMENT..... | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING..... | SUPPLEMENTARY WELL HISTORY..... | |
| NOTICE OF INTENTION TO ABANDON WELL..... | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 11, 1946

Well No. 1 is located 330 ft. from S line and 600 ft. from E line of sec. 27SE 1/4 Sec. 27 13 S 20 E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Forest Edwy County New Mexico
(Field) (County or Sub-division) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 421 feet of 8-5/8" casing. Cemented with 50 sacks of El Torro cement. Allowed cement to set 72 hours - drilled plug and found water completely shut off.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Forest E. LeversAddress Box 784Roswell, New MexicoBy Erwin J. Levan
Title Manager