Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

Land Office **Las Cruces**

Lease No. **037777a**

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

APPROVED
JUN 14 1965
[illegible signature] JR.
RUDOLPH ... ACTING DISTRICT ENGINEER

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	*Return to production*	
	~~fracturing~~	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ May 26 _____, 19 65

Well No. **Levers 3** is located __330__ ft. from **S** line and __1970__ ft. from **W** line of sec. 33

SE/4 SW/4 Sec. 33 (of Sec. and Sec. No.) 33 ____ **16S** (Twp.) ____ **29E** (Range) ____ **NMPM** (Meridian)

Cave
Forrest (Field) ____ **Eddy** (County or Subdivision) ____ **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Returned **well** to production and started pumping as response to water flood.

RECEIVED
JUN 1 · 1965
O. C. C.
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Highland Corp.**

Address **2211 West Grand**

Artesia, New Mexico

By *[signature] W. J. Jennington*

Title *Agent*