

NEW MEXICO OIL CONSERVATION COMMISSION
FIELD TRIP REPORT


C19F

I N S P E C T I O N	C L A S S I F I C A T I O N	F A C I L I T Y	H O U R S	Q U A R T E R
				H O U R S

Name GARY WILLIAMS Date 2/21/2002 Miles 130 District II
 Time of Departure 2:30 AM Time of Return 3:30 Car No. 4768
 MILES OUT 56405 MILES IN 56535

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

Per visual inspection the following wells are plugged and abandoned. No sundry notices were filed.


 Gary Williams, Field Rep I

H	O	O	1	2	1-Well 1-16-30 Stanford Nat Res. E. Houshord Unit Tract #3 Well is P+ A
H	O	O	1		1-Well 1-16-30 Stanford Nat Res E, Houshord Unit Tract 6 #1 Well is P+ A

<u>Mileage</u>	<u>Per Diem</u>	<u>Hours</u>
UIC _____	UIC _____	UIC _____
RFA _____	RFA _____	RFA _____
Other <u>130</u>	Other _____	Other <u>7</u>

TYPE INSPECTION PERFORMED	INSPECTION CLASSIFICATION	NATURE OF SPECIFIC WELL OR FACILITY INSPECTED
H - Housekeeping	U - Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SND, Indry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)	D - Drilling
P - Plugging	R - Inspections relating to Reclamation Fund Activity	P - Production
C - Plugging Cleanup	O - Other - Inspections not related to injection or The Reclamation Fund.	I - Injection
T - Well Test	E - Indicates some form of enforcement action taken in the field (show immediately below the letter U, R or O)	C - Combined prod. inj. operations
R - Repair/Workover		S - SND
F - Waterflow		U - Underground Storage
M - Mishap or Spill		G - General Operation
W - Water Contamination		L - Facility or location
O - Other		H - Hoisting
		O - Other

+