

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

copy to SF
Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection Well		5. LEASE DESIGNATION AND SERIAL NO. NM-06407-A
2. NAME OF OPERATOR McClellan Oil Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 2249, Wichita Falls, Texas 76307		7. UNIT AGREEMENT NAME East Henshaw Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FWL & 2006.6' FWL		8. FARM OR LEASE NAME Tract 6
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, (M, etc.) 3,963' DF		10. FIELD AND POOL, OR WILDCAT West Henshaw Grayburg
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA UL-F Sec.1 T16S R30E
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)		12. COUNTY OR PARISH Eddy
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) Convert to Water Injection	
(Other) <input type="checkbox"/>		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

December 1, 1976 2" tubing and an R-4 tension packer were run in this well and the packer set @ a depth of approximately 2,980' which is 50' above the top of the pay zone.

December 15, 1976 Water injection was initiated into the subject well at a rate of 75 BWPD.

RECEIVED

JAN 21 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

POSTED
ID-3
1-28-77

18. I hereby certify that the foregoing is true and correct

SIGNED Robert E. Graham TITLE Petroleum Engineer DATE 1/10/77

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side