

RECEIVED
OCT 26 1961
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Section 1

The summary on this page is for the condition of the well at above date

Commenced drilling June 28 1961 Finished drilling July 19 1961

No. 1, from 3-24 to 30381 (-) No. 4, from _____ to _____
No. 2, from _____ to _____ No. 5, from _____ to _____
No. 3, from _____ to _____ No. 6, from _____ to _____

No. 1, from _____ to _____ No. 3, from _____ to _____
No. 2, from _____ to _____ No. 4, from _____ to _____

[illegible]

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used
5/8	451'	200	Colliburton		Cement to surface
1 1/2	352'	130	Colliburton		
2 3/4	240'				

Heaving plug—Material ----- Length ----- Depth set -----
Adapters—Material ----- Size -----

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
Part. 204-330	wood with 15,000 gal. oil.	acidized with 200 gal.				

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet

Cable tools were used from _____ feet to 304.5 feet, and from _____ feet to _____ feet

July 15, 1901	Put to producing	1901
The production for the first 24 hours was	barrels of fluid of which	% was oil;
emulsion; % water; and % sediment.	Gravity, °Bé.	100
If gas well, cu. ft. per 24 hours	Gallons gasoline per 1,000 cu. ft. of gas	
Rock pressure. lbs. per sq. in.		

Ray Morris Drilling Co.	, Driller		, Driller
G. A. Jamps	, Driller		, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
—3—	150	150	Surface, Shale, and Red Bed
150	415	265	Red Beds and Anhy.
415	489	74	Anhy.
489	1358	869	Anhy. and Salt
1358	1777	419	Anhy., Gyp. and Salt
1777	2030	253	Anhy.
2030	2377	347	Anhy. and Gyp.
2377	2476	99	Anhy.
2476	2585	109	Anhy. and Lime
2585	3012	427	Lime
3012	3045	3	Sand
3045 TD			
			Tops: Yates 1544 Queen 2315 Grayburg 2710 Premier 3020

