



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las Cruces
Lease No. 069645
Unit Stablein

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Loco Hills, New Mexico November 13, 1957Well No. 2 is located 1650 ft. from S line and 330 ft. from W line of sec. 3SW/4 NW/4 SW/4 Sec. 3 16-S 30-E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Undesignated Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 3846 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On November 4, 1957 we ran 436' of 10 3/4" OD 32.75# 8rd thrd new H3 casing to 442' and cemented with 50 sacks cement.

After allowing to stand cemented for 72 hours, we drilled plug, bailed hole down and re-ran bailer.

As shut-off proved complete drilling was resumed.

Cementing was done by Denton Oil Well Cementing Co.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company GENERAL AMERICAN OIL COMPANY OF TEXASAddress P. O. BOX 416LOCO HILLS, NEW MEXICOBy R. J. Heard
R. J. Heard
Title District Superintendent.