


APPROVED



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office ~~New Mexico~~

Lease No. LC-060398-B

Unit Little Lucky Lake  
(14-08-001-4707)

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	Install Artificial Lift	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 22, 1963, 19

Little Lucky Lake Unit - Shell

Well No. 2 is located 3329 ft. from {N} line and 1980 ft. from {W} line of sec. 3

Lot 11 of Sec. 3

(1/4 Sec. and Sec. No.)

16

(Twp.)

30

(Range)

NMPM

(Meridian)

West Henshaw, Grayburg

(Field)

Eddy

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3668 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Installed Parkersburg OCS-D-15 Pumping Unit with 7½ h.p. electric motor on Huthco Portable Base.

RECEIVED

FEB 1 1963

O. C. C.  
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Texaco, Inc.

Address Box 3109

Midland, Texas

By

R. E. Hellman

Title Contractman