


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Las Cruces

JUL 29 1957

SUNDRY NOTICES AND REPORTS ON ~~WELLS~~ <sup>Oil Cons. Comm.</sup> OFFICE

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 24, 19 57

I. W. Bosworth

Well No. 4 is located 1980 ft. from ~~N~~S line and 660 ft. from ~~E~~W line of sec. 4SE/4 Sec. 4  
(1/4 Sec. and Sec. No.)T-16-S  
(Twp.)R-30-E  
(Range)NMPM  
(Meridian)Undesignated  
(Field)Eddy  
(County or Subdivision)New Mexico  
(State or Territory)

RDB

The elevation of the derrick floor above sea level is 3873 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On July 3, 1957, 5-1/2" casing was set at 2902 and cemented with 125 sacks regular. After WOC for 36 hours, tested casing before and after drilling plug with 1000 psi for 30 minutes. No drop in pressure. Resumed operations.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum CorporationAddress Box 68HobbsNew MexicoBy Randy NewkirkTitle Field Superintendent

Form 9-331a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Las Cruces**

Lease No. **867310**  
Unit **W E D**

**JUL 24 1957**

Oil Cons. Comm.  
MEXICO OFFICE

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**July 24**, 19 **57**

**I. W. Bosworth**

Well No. **4** is located **1980** ft. from **AX** line and **660** ft. from **E** line of sec. **4**

**SE/4 Sec. 4**  
(1/4 Sec. and Sec. No.)

**T-16-S**  
(Twp.)

**R-30-E**  
(Range)

**NMPM**  
(Meridian)

**Undesignated**  
(Field)

**Eddy**  
(County or Subdivision)

**New Mexico**  
(State or Territory)

**RDB**

The elevation of the derrick floor above sea level is **3073** ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On July 3, 1957, 5-1/2" casing was set at 2902 and cemented with 125 sacks regular. After WOC for 36 hours, tested casing before and after drilling plug with 1000 psi for 30 minutes. No drop in pressure. Resumed operations.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Pan American Petroleum Corporation**

Address **Box 68**

**Hobbs**

**New Mexico**

By **Ralph H. Newmark**

Title **Field Superintendent**