

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other instru-
verse side)PLICATE
JS on re-Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection	5. LEASE DESIGNATION AND SERIAL NO. NM 0560379
2. NAME OF OPERATOR Tenneco Oil Company ✓	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 1031, Midland, Texas 79701	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660" FNL & 660 FWL	8. FARM OR LEASE NAME SW Henshaw Premier Unit
14. PERMIT NO.	9. WELL NO. 6
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3774'	10. FIELD AND POOL, OR WILDCAT Henshaw West (Grayburg)
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T-16-5, R-30-E
	12. COUNTY OR PARISH Eddy
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) 4 1/2 Casing ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-25-69

Ran 88 Jts 4 1/2" OD, 10.5#, J-55 Csg to 2833' and Cemented W/200 sx Class C W/2% get plus 6" NACL/sx. Plug down at 4:12 PM 7-25-69. Pressure tested Csg to 1000 psi for 30 min after WOC 18 hrs. Held ok. Top of cement is 1940' by temp survey.

RECEIVED
AUG-4-1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

L. M. Williams

TITLE Production Engineer

DATE 7-31-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

ACCEPTED FOR RECORD PURPOSES ONLY
AUG 4 - 1969
Date
ACTING District Engineer

*See Instructions on Reverse Side