

[illegible]

STATE N. M.	COUNTY Chelly	ELEVATION	Desc. By Vilas P. SHEDDEN Artesia, New Mexico	COORDINATES Leonard P. Co.
KIND OF SAMPLE Rotary	LOCATION	S 18	T 16	R 30
FARM Kagerty			WELL NO. 4	

DEPTH	DOLO	LIME	Description	SALT		SHALE				SAND		CMT.	NOTE
				%	%	Red	Gry.	Grn.	Blk.	Red	Gry.		
2785-96										100	silty		
97-100			Mottled ph. f. & c.										
98-100			Buff f. v. w. grey sd. lenses										
99-100			Ph										
2799-00	100		Buff										
2800-01	100												
2801-02	100		Red sdy. w. buff										
2802-03	100		Ph f. & c.										
2803-05	100		Buff										
2805-10	100												
2810-11	100		sd.										
2811-12	100		sp. sandy.										
2812-17	100		f. & c.							10	90	grit silty sandy.	
2817-18										to	100		
2818-19										100			
2819-20													
2820-21	100		L										
2824-25	100		red										
2825-26	100		L										
2826-27	100		L										
2827-28	100		Ph										
2828-31	100		Buff										
2831-32	100		Ph										
2832-45	100		Buff										