

(SUBMIT IN TRIPLICATE)

U. S. Land Office ArtesiaFederal Virginia P. H.  
Carpenter et al.UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLease or permit No. LC-028940

Co. #72016

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, May 29, 1944Well No. 1 is located 1980 ft. from N line and 1980 ft. from E line of sec. 20SW/4 of NE/4 of Sec. 20 16-S 30-E

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Square Lake Wildcat

(Field)

Eddy

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3775 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tested 7" casing by bailing dry on May 28, 1944 after allowing cement to set 111 hours.

Tested satisfactory.

GEOLOGICAL SURVEY  
RECEIVED  
JUN 10 1944GEOLOGICAL SURVEY  
RECEIVED  
JUN 1 - 1944  
Artesia, New Mexico

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining CompanyAddress Box 1600, Midland, TexasBy [Signature]Title Division Superintendent