

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 063925

Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED
SEP 10 1948

SUNDRY NOTICES AND REPORTS ON WELLS
GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 9, 1948, 19____

#1 Etz

Well No. 1 is located 560 ft. from N line and 660 ft. from E line of sec. 25

SW SW 25 16 S 30 E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Square Lake Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3839 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Above well was completed 10-25-40 for an initial of 4,000,000 feet of gas at T.D. 3081. I was ordered by the USGS to shut the well in about June 1, 1942 and the well has not been produced since. I now request permission to plug and salvage the casing.

10" casing was cemented at 495, and 7" cemented at 2430.

Will kill what gas is present with mud and place a 15 sack cement plug at show of 7" casing, shoot same around 2000 feet and mud to base of salt and place 10 sack cement plug, mud to base of 10" and place 10 sack plug. Shoot 10" where ever it will come and mud to the surface, place required marker and clean up location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. B. Mulcock,

Address Artesia, New Mexico.

By J. B. Mulcock
Title Owner.