

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 063925  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 2, 1949

Well No. 1 is located 660 ft. from N line and 630 ft. from E line of sec. 25  
SW SW 25 16 S 30 E NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Square Lake Eddy N. Mex.  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3839 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tubing was run in hole and hole mudded to surface and cement plug of 15 sacks placed at base of 7" casing. <sup>300</sup>Part of 7" casing was pulled and cement plug of 10 sacks placed at base of salt, and another cement plug of 10 sacks was placed at top of salt. <sup>30</sup>A few joints of 10" casing was pulled, hole was filled with mud and regulation marker was set in cement.

U. S. GEOLOGICAL SURVEY  
RECEIVED  
MAY 18 1949  
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company J. B. Mulcock

Address Artesia, New Mexico

By J. B. Mulcock  
Title Owner